



Photograph 1: Heavy rain occurred 1/17/12. No work was conducted other than checking stormwater controls.



Photograph 2: rain water pooling in equipment tracks.



Photograph 3: Contaminated soils not directly loaded and removed were covered with plastic.



Photograph 4: Stormwater controls worked well to prevent sediment runoff on to 1st Street.



ENVIRONMENT & INFRASTRUCTURE, INC
2533 Greer Road, Suite 6
Tallahassee, Florida 32308

PHOTO DOCUMENTATION – 1/20/2012
SHADD PROPERTY & VICINITY
220 WEST MAIN STREET
LAKE BUTLER, UNION COUNTY, FLORIDA
FDEP FACILITY ID NO.: 63 9807182
MACTEC PROJECT NO.: 6090110001



Photograph 5: Stormwater controls at the corner of Main Street and 2nd Avenue. .



Photograph 6: Street side of the excavation on Main Street.



Photograph 7: Stormwater controls on 2nd Avenue.



Photograph 8: 1st Street.



ENVIRONMENT & INFRASTRUCTURE, INC
 2533 Greer Road, Suite 6
 Tallahassee, Florida 32308

PHOTO DOCUMENTATION – 1/20/2012
SHADD PROPERTY & VICINITY
 220 WEST MAIN STREET
 LAKE BUTLER, UNION COUNTY, FLORIDA
 FDEP FACILITY ID NO.: 63 9807182
 MACTEC PROJECT NO.: 6090110001