



Photograph 1: Test pit to determine static water table (~17 feet bls) for setting dewatering pumps.



Photograph 2: Dewatering manifold is shown to right along jersey barriers.



Photograph 3: five inch diameter dewatering wells are seen close and far.



Photograph 4: Shadd excavation at approximately 10 feet bls.



**ENVIRONMENT &
INFRASTRUCTURE, INC**
2533 Greer Road, Suite 6
Tallahassee, Florida 32308

PHOTO DOCUMENTATION – 2/3/2012
SHADD PROPERTY & VICINITY
220 WEST MAIN STREET
LAKE BUTLER, UNION COUNTY, FLORIDA
FDEP FACILITY ID NO.: 63 9807182
MACTEC PROJECT NO.: 6090110001



Photograph 5: Shadd excavation approximately 2/3 of the way back to 10 feet bls.



Photograph 6: Shadd excavation.



Photograph 7: Shadd excavation, showing sloping in southeast side of excavation.



Photograph 8: Shadd excavation.



**ENVIRONMENT &
INFRASTRUCTURE, INC**
2533 Greer Road, Suite 6
Tallahassee, Florida 32308

PHOTO DOCUMENTATION – 2/3/2012
SHADD PROPERTY & VICINITY
220 WEST MAIN STREET
LAKE BUTLER, UNION COUNTY, FLORIDA
FDEP FACILITY ID NO.: 63 9807182
MACTEC PROJECT NO.: 6090110001