



Photograph 1: Repair of a water line that was not located by public or private locate entities.



Photograph 2: Some water lines were not located. BBES hand dug for visual locate.



Photograph 3: Multiple water line to each of the site buildings and others on adjacent properties.



Photograph 4: Drilling a LDA hole east of the fuel lines and west of the water line.



**ENVIRONMENT &  
INFRASTRUCTURE, INC**  
2533 Greer Road, Suite 6  
Tallahassee, Florida 32308

P:\COM SHARED\PRE-APPROV\LAKE BUTLER\2011\SHADDSWELL ABANDONMENT PHOTOS.DOCX


PHOTO DOCUMENTATION - 2/3/12  
**COASTAL MART (AKA SUNRISE FOOD MART)**  
260 WEST MAIN STREET  
LAKE BUTLER, UNION COUNTY, FLORIDA  
FDEP FACILITY ID NO.: 63 8517149  
MACTEC PROJECT NO.: 6090100067




Photograph 5: LDA holes are backfilled through a metal grate for safety.



Photograph 6: Preparing to drill a LDA hole in front of the laundry mat.



Photograph 7: NA



Photograph 8: NA



**ENVIRONMENT &  
INFRASTRUCTURE, INC**  
2533 Greer Road, Suite 6  
Tallahassee, Florida 32308

PHOTO DOCUMENTATION – 2/3/12  
**COASTAL MART (AKA SUNRISE FOOD MART)**  
260 WEST MAIN STREET  
LAKE BUTLER, UNION COUNTY, FLORIDA  
FDEP FACILITY ID NO.: 63 8517149  
MACTEC PROJECT NO.: 6090100067